INSTRUCTIONS FOR INSTALLING AN ACMRTRON"™, SERIES 600, COIN MECHANISM REPLACEMENT KIT IN A NATIONAL VENDORS ®, MERCHANDISER EQUIPPED WITH A MECHANICAL ACMR COIN MECHANISM

CHECK THE PARTS RECEIVED IN THE KIT WITH THE PARTS LIST IN THESE INSTRUCTIONS. FIGURE 1 SHOWS ALL THE PARTS IN THE KIT. IF ANY PARTS ARE MISSING, CONTACT NATIONAL VENDORS' PARTS DEPARTMENT IMMEDIATELY.

Kit number 5580070 contains the following:

Part	Number	Description	Quantity
55800	069	Installation	1
5580	n 6.8	Instructions ACMR Instruction	1
יטטכנ	000	Label	1
5580	067	ACMR Adaption	
5500	0/0	Harness End Arm Cam	1
5580	000	Washer	1
5580	056	Cam & End Arm	-
		Assembly	1
5580	001	ACMRTRON"TM" Series 600	1
6131	143	Cable Clamp	3
2204		Self-clinching	_
		wire tie (medium)	1
5580	072	Lubricant	1

INSTALLATION

1. Disconnect the Merchandiser Cord from the Service outlet. Open the Cabinet door and remove the Mechanism Assembly.

-CAUTION-

The Mechanism Assembly is heavy. To prevent injury, use two people to remove or replace the Unit.

Take the ACMR Adaption Harness and the Cable Clamps, included in the Kit, and install as shown in Figure 2.

NOTE

The Adaption Harness has been made to accomodate various Merchandisers. If excessively long, take up the slack and tie together with the wire tie included in the Kit.

After completing the above, remove the Slug Rejector and the ACMR from the sidewall of the Mechanism Assembly. Retain the screw and wing nut, they will be used to attach the new coin unit. Once the sidewall is exposed, remove the Slug Chute Assembly.

NOTE

Retain all the other parts requiring removal, they will be reassembled once the Slug Chute Assembly has been removed.


See Figure 3A, 3B, and 3C for the various configurations.

Before proceeding to the next step, check the Coin Handling Mounting Brackets and adjust them to their highest limits. See Figure 3A, 3B, and 3C. In some installations, when the Coin Return Knob is pulled down, after making a test vend, the Coin Return Door will not fall. In these situations the Coin Handling Mounting Brackets should be adjusted to their lowest limits.

Take the new coin unit and mount it on the sidewall using the Cam & End Arm Assembly; the new, yellow, End Arm Cam Washer; both supplied with the kit, plus the screw and wing nut previously removed. See Figure 4. Replace the Slug Rejector.

NOTE

Check the REAR Slug Rejector Bracket before replacing the Slug Rejector. If there is a washer between the Bracket Spacer and sidewall, remove it. See Figure 4.




ACMRTRON INSTRUCTION LABEL 5580068 (1)



CAM & END ARM ASSEMBLY 5580056 (1)



END ARM CAM WASHER 5580060 (1)




ACMRTRON SERIES 600 5580001 (1)





CABLE CLAMP 6131143 (3)



ACMR ADAPTION HARNESS 5580067 (1)




FIGURE 2




FIGURE 3A

7 4 of 10





FIGURE 3B






FIGURE 4

7 of 10

4. Put the Mechanism Assembly back into the Cabinet.

CAUTION

The Mechanism Assembly is heavy. To prevent injury, use two people to remove or replace the Unit.

Attach the Adaption Harness to the Coin Unit.

- 5. The Label, included in the Kit, contains the General Information and Price Setting Instructions for the ACMRTRON. It should be mounted inside the Merchandiser, perferably on the Door. See Figure 5.
- 6. As mentioned on the Label, make at least one test vend of the coin unit before returning the Merchandiser to service. If unable to make a test vend, proceed with the following:
 - A. Rotate the End Arm Cam clock-wise. See Figure 6.
 - B. Pull out on a Selection Knob until the ratchet on the sidewall is locked in the first tooth on the Rack Plate Assembly. See Figure 7.
 - C. Check the position of the Cash Box Door Cam. If the pin is too far down in the slot, turn the End Arm Cam counter-clockwise. See Figure 6.
 - D. Make a test vend.
 - E. Pull down on the Coin Return Knob. The Coin Return Door should fall.
 - F. Repeat step B.
 - G. Pull down on the Coin Return Knob. The Coin Return Door should remain in place.




FIGURE 5

- WARNING -

This equipment generates, uses, and can radiate radio frequency energy, and if not installed and used in accordance with the Instructions, may cause interference to radio communications. It has been tested and found to comply with the limits for a Class computing device pur-Subpart J of Part 15 of suant to These rules are the FCC Rules. provide reasonable designed to protection against such ference when operated in a commercial environment. Operation of this equipment in a residential area is likely to cause interference. In these cases the user, at his own expense, will be required to take whatever measures necessary to correct the interference.




FIGURE 6




FIGURE 7
10 of 10

This Kit was designed to accomodate the Merchandicers	
that come off our assembly Line and have not been	4
that come off our assembly Time and have not been altered in any way. If, for any reason, parts	
have been removed, this Kit may not perform as indicated;	

Larry Called The following suggestion in.
a large number of operators have 222
and 800 cie units That have The Price sheft
arm springs removed and They may possible have
lost The removed springs. When The aCMR 600
Is installed it may not work on low price
due To This fact.
He Seals That some instructions should be
added To warn operators That with out The
Springs The low price may not vend.
in the state of the said of the



Signature:

PHONE CALL REPORT	
CUSTOMER: ALL REPURI COPY TO: B. Smit H. Pryot B. Bell	
ADDRESS: The T. Flee City Zip Zip Zip Zip	
I Talked To: Larry Cohen	
About Machine Model: ACMR 600 Serial No. — Larry Called The following suggestion in.	
a large number of operators have 222	
and 800 cip units That have The Price shaft	
lost The removed springs. When The QCMR 60.	ى
Jue To This fact.	
He Seals That some instructions should be added To warn operators that with out The	<u> </u>
Springs The low price may not vend.	



Signature: Signature: