

CAUTION:

When installing this PCB in 455 models, please be sure that you are using 158.22 or newer software. Prior software versions may cause a short cycling of the compressor when used with this new board.

9980030

CAUTION:

When installing this PCB in 455 models, please be sure that you are using 158.22 or newer software. Prior software versions may cause a short cycling of the compressor when used with this new board.

9980030