



CRANE National Vendors

SERVICE BULLETIN

12955 Enterprise Way
Bridgeton, MO 63044-1200


Technical Service (800) NAT-VEND
Parts (800) NA1-PART
Sales/Parts Fax (800) 531-2580
General Information (800) 325-8811

B1579902

Tray Rail PCB Shield

April 26, 1999

The right hand tray rail assembly on all snack and combination merchandisers has been updated with the addition of a tray rail pcb shield effective April 26, 1999. This change will eliminate the possibility of snagging the tray harness when removing a product tray for servicing.



This change took effect with the following serial numbers:

157-028026	465-081822
158-023093	484-012294
464-080933	497-011868

The changes described in this document are recommended to be performed to machines produced prior to this starting serial number. Parts to perform these modifications are available at no cost from the National Vendors Parts Department. The cost of any labor to perform this change is the responsibility of the current machine owner.

John Naughton
Service Department