



# CRANE National Vendors

## SERVICE BULLETIN

12955 Enterprise Way  
Bridgeton, MO 63044-1200

Technical Service (800) NAT-VEND  
Parts (800) NA1-PART  
Sales/Parts Fax (800) 531-2580  
General Information (800) 325-8811

---

**B3279902****Cabinet Interface PCB****May 27, 1999**

The cabinet interface PCB for the Cold Drink Center, part #3286007 has been revised in order to eliminate the potential for "Runaway" syrup pumps.

The circuit on the revised PCB, part # 3286009 has a metal oxide varistor added across the triac drive circuit for the motor driven syrup pumps.

This change started with the following machine serial #'s

<b>Domestic</b>	<b>327-010060</b>
	<b>328-010196</b>
<b>Foreign</b>	<b>328-080073</b>

All machines produced prior to this change will be modified by National Vendor's personnel. A National Vendors' employee will be in contact with customers that have purchased these machines in order to arrange for the performance of this modification. Parts to perform this modification will be provided free of charge. Labor will be provided by National Vendors' employees. National Vendors will not pay the cost of any labor to perform these modifications unless prior arrangements have been made in writing with a Regional Vice-President.

John Naughton  
Service Department