

DIXIE - MARCO, INC.
SERVICE BULLETIN # 109

Date: April 21, 1970

MODEL: Bonanza IV

SUBJECT: Bonanza Wheel Kit - Clearance - Louvre Screw
VS Wheel.

Due to field complaints, reference above subject, ie., on some Bonanzas, it was difficult to remove the Wing Screw from the louvred panel because the wing of the screw struck the wheel as it was being turned out.

On Warehouse Stock "Wheel Kits" the following will be done immediately:

1. Provide (4) four Ph. Tr. Hd. St. Stl. Screws (900,900,220.02) in an envelope.
2. A slip of paper will be placed in the envelope indicating "optional screws for attachment of side louvre panels".

On the next production run of "Wheel Kits" the legs of the wheel mounting bracket will be lengthened so as to increase the distance between the bottom of the Bonanza and the center line of the wheel axle by 3/8" resulting in sufficient wing screw - wheel clearance.

Service Department
Dixie - Marco, Inc.