

DIXIE - MARCO, INC.
SERVICE BULLETIN #111

April 22, 1970

MODELS AFFECTED:

DNS Slant Shelf Bottle Venders

REASON:

To Provide a Positive Means For "Bottle Roll Down"
For Those Locations Experiencing "Cocked" bottles or
"Hang Up" on the Feed Shelf.

ORDER AS:

B/M 96,011,400.04 - Replacement Feed Shelf

Kit Consists of:

- a. One (1) C1190.06 Feed Shelf
- b. One (1) E1200.06 Bottle Spacer
- c. One (1) 900,900,410.01 Dart Clip

Service Department
Dixie - Marco, Inc

Rq. 282

Dijie Marco
Service Bulletin # 111

4-21-70

Models affected: DNS - Slant Shelf Bottle Venders

Reason: To Provide a Positive Means
For "Bottle Roll Down" For Those

Locations Experiencing "Cocked" bottles
or "Hang Up" on the Feed Shelf.

order as: B/M 96, ~~904~~, 900.04 - Replacement
Feed Shelf

Kit consists of:

- one (1) C1190.06 Feed Shelf
- one (1) B1200.06 Bottle Spacer
- one (1) 900, 900, 410.01 Dart Clip