

DIXIE - MARCO, INC.  
SERVICE BULLETIN # 116

Date: May 4, 1970

MODEL AFFECTED: Bonanza IV

REASON: To make available ( For Ordering Purposes ) Information outlined below. To date three (3) different compressor models ( Tecumseh ) have been used on the Bonanza.

| <u>Compressor<br/>Model</u> | <u>Relay</u> | <u>Overload</u> | <u>Capacitor</u> |
|-----------------------------|--------------|-----------------|------------------|
| AP 3311                     | 82639        | 83631           | NOT REQUIRED     |
| AE344CA                     | 8209660A09   | 83COMRTA78      | NOT REQUIRED     |
| AE4440A                     | 82632        | 83COMRTA78      | 85657-1          |

DIXIE - MARCO, INC.  
SERVICE DEPARTMENT