

DIXIE-NARCO, INC.  
SERVICE BULLETIN #140

DATE: April 28, 1972

MODELS: All Adaptables  
All Serpentine

SUBJECT: Scratching of top of vender in transit.

REASON: Adding of waxed paper to prevent scratching.

From time to time, we have received complaints that our venders were being scratched on the top during transit.

To prevent this from occurring, we have added waxed paper to the top of all venders.

This procedure was started in February of 1972 and production order #1684.60.

Dixie-Narco, Inc.  
Service Department