

# DIXIE-NARCO

## Service Bulletin # 177

Date: January 10, 1975

MODELS: All Adaptables (With Security Door)  
All Serpentine With Security Door

SUBJECT: Coinco S-75 Coin Changer

REASON: To make everyone aware of a field problem caused by  
Coinco's S-75 Coin Changer, as reported by a customer.

THIS IS

WHAT HAPPENS: By "kicking" or "beating" the Vender Door in  
the Coin Changer Area the S-75 may set up a  
Credit.

Result - - - "FREE VEND"

Coinco has since corrected the problem but you could  
encounter it on earlier models of the S-75. If so,  
make sure that the Area Coinco Representative is  
notified either by you or the Bottler Service Manager.

Fact: We know of no single instance where the Problem outlined above  
is the fault of the Dixie-Narco "Models" indicated.

Dixie-Narco, Inc.  
Service Department