

Service Bulletin

W422

July 25, 1991

**TOMORROW'S
MANUFACTURING
LEADERSHIP
TODAY**

SUBJECT: 240v/50 Hz Williston Built Venders Serial Plate
Refrigerant Specification

MODELS AFFECTED: All Williston built 240v/50 Hz export venders built
prior to production run 6024 (July 1, 1991).


EXCEPTION: 90 DNCB 276 Diet Coke Tamworth Staff venders on production
run 6024. See page 2.


REASON: To enable customers to identify subject venders with serial
plates incorrectly listing R500 as refrigerant used to charge
system and correct this by placing an R12 OZ. label to show
correct refrigerant used to charge system.


ORDER AS: A903,829,570.01 R12oz Label

TO CORRECT:

1. On subject venders locate both serial plates:
 - a. Serial plate on left side of main door.
 - b. Serial plate on refrigeration base plate.
2. Locate the refrigerant specification on the serial plates;
See "A" below.



3. Place new R12 OZ. label supplied 
over R500 refrigerant specification on each serial plate.
See "B" below.




EXCEPTION: 90 DNCB 276 Diet Coke Tamworth Staff venders on production run 6024 (July 1, 1991).

REASON: To provide an R12 OZ. label for serial plate to show refrigerant used to charge system.

TO CORRECT:

1. On subject venders locate both serial plates:
 - a. Serial plate on left side of main door.
 - b. Serial plate on refrigeration base plate.
2. Locate the area on serial plate that would typically have refrigerant specification. See "A" below.



3. Place new R12 OZ. label supplied



over refrigerant specification area on each serial plate. See "B" below.

