

Technical Bulletin

Bulletin Number: <u>432</u> Revision	Number: R-00
	on Date:

SUBJECT: NEW VERY FINE CIRCULAR SELECT BUTTONS

MODELS: All Very Fine Circular Venders Serialized 0001-3194 to 0001-3233.

REASON: To install a select button that cannot be pushed in a manner that causes the button to go

beyond the back of the control panel and stick.

BUTTON REPLACEMENT

1. Unplug vender.

- 2. Remove existing select button from the vending machine. (Return buttons to Dixie-Narco.)
- 3. Install new select button in vending machine. (Part # 801,806,760.11) Ensure sold out lamp is locked in position.
- 4. Repeat steps 2 and 3 for all remaining select buttons.
- 5. Plug in vender.
- 6. Test each selection to insure proper function of new select button.

