



CRANE National Vendors

SERVICE BULLETIN

12955 Enterprise Way
Bridgeton, MO 63044-1200

Technical Service (800) NAT-VEND
Parts (800) NA1-PART
Sales/Parts Fax (800) 531-2580
General Information (800) 325-8811

B1579901**Product Identifier Labels****April 15, 1999**

The raw material used in the Product Identifier Labels has been changed in order to reduce the possibility for discoloration that may occur when exposed to high levels of ultra-violet light. This change took effect approximately April 15, 1999 and the new parts are currently available for purchase from the National Vendor's Parts Department.

The part number(s) of the new Product Identifier Labels are listed below:

| <u>Part #</u> | <u>Description</u> |
|----------------------|---------------------------|
| 157-7047 | Label Items A0 - A9 |
| 157-7048 | Label Items B0 - B9 |
| 157-7049 | Label Items C0 - C9 |
| 157-7050 | Label Items D0 - D9 |
| 157-7051 | Label Items E0 - E9 |
| 157-7052 | Label Items F0 - F9 |
| 157-7053 | Label Items G0 - G9 |

This change is being implemented as part of our ongoing product improvement process and is not a required update to older machines. If the current owner of a machine chooses to update a machine with this improvement, it is solely at their discretion. Parts are available for purchase from the National Vendor Parts Department and any labor to install or modify any existing equipment is the owner's responsibility.

John Naughton
Service department