

Service Bulletin

Technical Service (888)GPL-LINE Parts (800) 621-7278 Parts Fax (800) 531-2580 General Information (800) 325-8811

12955 Enterprise Way Bridgeton, MO 63044-1200

Issue 106 November 30, 1998

The color of the drive cam on all "Snack" motors (P/N 1577035) has been changed from white to blue. The cam on the "Food Module" motor (P/N 4744555) will remain white. Our motor supplier made this change as an identification tool in their assembly process.

The location of the switch mount has been changed on the blue cam "Snack" motor to provide a better switch actuation.

Scott Kearns GPL Service Department