

SERVICE INFORMATION

M134.0

MODELS AFFECTED: All BevMax 4/3 Model Venders.

MODEL NUMBERS: DN5800/3800 – BevMax 4/3 Venders

Released: 8/26/14

RE: Crane Merchandising Systems DN5800/3800-4 & DN5800/3800-3
Delivery Cup Deflector.



Reason: To provide installation instructions when installing the Delivery Cup Deflector. This is used for packages tipping and not making it in the Delivery (Picker) Cup. This problem is seen with the new taller bottles with a higher center of gravity and wider diameter at the shoulders. If you have any issues please contact your Crane Merchandising Systems Representative or the Technical Service Department at 803-266-5001.

Order: 1 – CR0023167 BevMax 4/3 Cup Sleeve Deflector



CR0023167
Cup Sleeve Deflector

Figure 1

SERVICE INFORMATION

Installation:

1. Deliver Cup Sleeve Deflector should be installed with the longer end inside the cup sleeve and should be justified to the corner closest to the cup body. (see Figure 2).



Note positioning of the deflector inside the cup sleeve and closest to the cup. Inside view.

Figure 2



Note positioning of the deflector inside the cup sleeve and closest to the cup. Outside view.

Figure 3

IMPORTANT: As always, please remember to check the following: vender is level; trays are secured front & back; delivery cup alignment to gate; slides for wear, flash, burrs, pitting, dirt, grime, or syrup; slide is flush to chassis; gate pins are seated; gear box for smooth operation; trigger in delivery cup for sharp edge or flash; power supply to vender; and clean and lubricate the slides. Refer to Service Instruction M101.0 for details on these procedures.