

SERVICE INFORMATION



BULLETIN NO. 126

DATE: 03/02

75 West Plato Blvd. St. Paul, MN 55107
300 Jacksonville Rd. Warminster, PA 18974

RE: 223 Café Diem™

SUBJECT: BREW VALVE DESIGN CHANGE

Effective July 13, 2002 for the model APi 223 Hot Beverage Merchandiser, several product improvements were introduced. These improvements were designed to improve consistency in the drink levels. ***It is highly recommended that all the parts be replaced as a kit.***

The new brew valve has larger inlet and uses two purple o-rings (part # 14759) on the valve stem. The vent hole is on the left side, which requires the new brew valve bracket, (part # 22001086).

The Brewer Spout was remolded to have a fixed inlet instead of inserting the brew hose down into the spout. This will help eliminate backpressure or the potential for obstruction and improve water flow.

Replacement of the grommet is mandatory, and the existing hose should be trimmed to 10.25 inches, and any wire tie on the end of the hose should be removed.

This kit will be available for a three-month period at no charge, ending on May 31, 2003. You can order this **Kit #27500068** from your authorized APi distributor or from the Spare Parts Department in Warminster, Pa. There will be a maximum of 20 kits per order and will be billed out as advance replacements, until the old valves are returned for credit. At the end of this period, normal warranty practices will apply.

This kit includes the following parts:

ITEM	QTY	PART NUMBER	DESCRIPTION
A	1	22001086	Brew Valve Bracket
B	1	26700014	Brew Valve Complete
C	1	24400044	Grommet Brew Valve
D	1	26600440	Brew Water Spout
	1	27500068-INS	Installation Instructions

It is highly recommended that all the parts be replaced as a kit!

