

SERVICE INFORMATION



75 W. PLATO BLVD. ST. PAUL, MN 55107
300 JACKSONVILLE RD. WARMINSTER, PA 18974

BULLETIN NO. 378

DATE: 07-99

RE: 320

SUBJECT: Thermal Door Latch

We have recently introduced a new thermal (inner) door latch into production. The new latch is a smaller $\frac{1}{2}$ turn latch that allows for adjustment to insure a tight seal.

The new latch is not interchangeable with the old latches without replacing the entire thermal window. The old latches will continue to be available as a parts item.

The new latch P/N is 13100003, and is common between the top and bottom. The Old latches are a separate part number for the top and bottom. Both the old and new latches are shown in the 320 service manual version 4.0 dated 2/99.

This new latch was introduced into production effective 03/30/99, serial # 32099089000.