

FRIGIDAIR, INC.
SERVICE BULLETIN #135

Date: October 12, 1971

MODELS: Executive with Ice-C-Vend 265

SUBJECT: Modified Lower Ice Chute

REASON: To prevent ice from falling through the notch in the lower ice chute into the Vender.

ORDER AS: B120,040,250.53 Lower Ice Chute with Teflon Installed.

KIT CONSISTS OF: 1 B120,040,250.53 Lower Ice Chute
1 801,900,360.01 2-1/2" x 22" Teflon - Installed
in Chute.

NOTE: See Service Bulletin #135.

Frigidaire, Inc.
Service Department