

DIXIE-MARCO, INC.
SERVICE BULLETIN #137

Date: November 26, 1971
Revised Date: December 1, 1972

MODELS: All Automatics as DN174-6; DN204-6; DN246-6 and DN408-6

SUBJECT: Modified Junction Box (9 relay junction box) to adapt the Junction Box to the Automatics.

REASON: To make available a relay junction box which is not subject to "Free Vend" as a result of "hammering on" the front of the Access Door.

KIT CONSISTS OF:

* 1	D1300.06	Relay Junction Box
1	901,900,550.01	Cable Clamp
5	900,200,320.01	#8 Soms Screw
1	B1300.06	Mounting Instructions

* Revised part number on 12/1/72
(Ref. EM/147,010,400.04)

Dixie-Marco
Service Dept