## DIXIE-NARCO.

## Service Bulletin # 186

MODELS: All Adaptables

SUBJECT: Two Bar Linkage - Vend Motor Assembly

(Replaces Cam)

REASON: To provide a simple bar linkage to drive the oscillator

assembly as opposed to the cam drive.

EFFECTIVE: DN174-6

Beginning Serial Number 1936001

DDDB300-6


(That is, both models will be in the

1936\_\_\_ run.)

On 5/7/75 Service started shipping subject 6 Stack

Vend Motors.

Subject Vend Motors (5 and 6 Stack) are interchangeable on all respective 5 stack and 6 stack Adaptables.



JAM

TWO (2) BAR LINHAGE

Since the appearance Cam vs Bar linkage is quite different, the information contained hereon is simply in keeping with the policy of keeping you informed.