


Dixie-Narco®



Lawrence Street (304) 725-3481
Ranson, West Virginia 25438 204 (800) 624-0553

Service Bulletin # 204 ate: August 3, 1977

MODELS: Adaptables

SUBJECT: Support Board (Wood)

REASON: To locate a Board between bottom of Main Door and top of Cabinet Base so that Board would remain in position during shipment thus supporting Main Door. This is to relieve excessive pressure on Tee Handle, Threaded Stud and Nut (on cabinet) into which the Stud threads.

BEGINNING SERIAL NUMBER: 001-2100

Service Department
Dixie-Narco, Inc.