

Dixie-Narco®



Lawrence Street
Ranson, West Virginia 25438

(304) 725-3481
(800) 624-0553
226

Service Bulletin # Date: June 4, 1980

MODELS: All Red Cam Dual Adaptables with Narrow Column

SUBJECT: Vend Rotor, for Narrow Column, redesigned to advance the Rotor approximately 5° further upon completion of the first cycle -- dispensing 12 oz. cans.

ORDER AS: D801,200,980.41 Vend Rotor

REASON: To supply a Vend Rotor to correct a problem which occurs only,

- a. In the Extreme Right Narrow Column
- b. While Dispensing the RIMMED 12 oz. can
from the Extreme Right Narrow Column

In
Combination

PROBLEM: a. Front Can Does Not Dispense.
b. On Next Cycle, 2 Cans Dispense.

KEEP IN MIND: a. Problem is the exception - not the rule.
b. Condition is very marginal.
c. Condition can be intermittent.
d. Do Not assume that problem will occur on all venders with Narrow Column.