

Technical Bulletin

Bulletin Number: 404 Revision Number: R-02

Release Date: January 3, 1990 Revision Date: March 15, 1993

SUBJECT: USA BILL VALIDATOR MOUNTING IN VERY FINE CIRCULAR VENDERS.

MODELS AFFECTED: All Very Fine Circular Venders

SERIAL NUMBER BREAKS:

- A. 0001-3194CO to 0001-3233DP
- B. 0001-6084CQ and up
- C. 0001-6000BO to 0001-6084CQ

REASON: To provide information on how to mount the USA Bill Validator in the Very Fine Circular vender.

**TO INSTALL USA VALIDATOR IN OPENING PROVIDED:
A. 0001-3194CO TO 0001-3233DP
B. 0001-6084CQ AND UP
(SEE FIGURE ON PAGE 2.)**

1. Unplug the vender.
2. Remove the coin insert retainer.
3. Remove the validator hole filler plate.
4. Install validator gasket (part #902,001,110.11).
5. Install rain diverter shelf (part #801,902,240.11).
6. Install four (4) white standoffs (part #801,804,860.01) i.e. one (1) on each validator mounting stud.
7. Place USA validator in position.
8. Secure with four (4) #8-32" keps nuts (part #900,800,500.01).
9. Plug in USA validator.
10. Plug in vender and test for proper operation.

**TO INSTALL USA VALIDATOR IN OPENING PROVIDED:
C. 0001-6000BO TO 0001-6084CQ
(SEE FIGURE BELOW.)**

1. Unplug the vender.
2. Remove the coin insert retainer.
3. Remove the validator hole filler plate.
4. Install validator gasket (part #902,001,110.11).
5. Install rain diverter shelf (part #801,902,240.11).
6. Place USA validator in position.
7. Secure with four (4) #8-32" keps nuts (part #900,800,500.01).
8. Plug in USA validator.
9. Plug in vender and test for proper operation.

VIEW FROM INSIDE OF MAIN DOOR

