

Technical Bulletin

Bulletin Number: <u>441</u> Revision Number: <u>R-00</u>

Release Date: September 21, 1992

Revision Date: _____

SUBJECT: EXTERNAL RETAINING RING (E-RING) FOR T-HANDLES

MODELS AFFECTED: All Models

<u>REASON:</u> To make available an E-ring with increased strength to combat vandal entry by prying door.



TO INSTALL:

- 1. Remove T-handle from T-handle body.
- 2. Remove existing E-ring. See section "A", figure 1.
- 3. Install new external retaining ring in its place.

