


Technical Bulletin



**TOMORROW'S
MANUFACTURING
LEADERSHIP
TODAY**

Bulletin Number: 459 Revision Number: R-00
Release Date: Oct. 29, 1992 Revision Date: _____

SUBJECT: TRIM FOR ACCESS HOLE OF REAR CONDENSER BAFFLE

MODELS AFFECTED: All Models With Permanent Baffling System


REASON: To provide trim to cover metal edge of the access hole of the rear condenser baffle.

SERIAL BREAK: Beginning serial number 0001-6099DQ and up, the trim for the access hole will be factory installed.

Part Number: 801,807,100.21 Trim-Access Hole

TO INSTALL:

1. Locate access hole on back of vender.
2. Bend the trim in a "L" shape to match the metal edge of the access door.
3. Snap trim in position over the metal edge of the access hole.



Trim
#801,807,100.21

IMPORTANT: On some venders the trim may be too long. The trim can be cut to fit these venders.